

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Poker Lake Unit 140 Tank Battery (2RP-2072)	Facility Type: Exploration and Production	
Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-105-29876

LOCATION OF RELEASE

Unit Letter E	Section 32	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------


Latitude N 32.263302 Longitude W 103.910493

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 Bbls produced water	Volume Recovered: 5 bbls from the impervious containment.
Source of Release: 3" water transfer poly line	Date and Hour of Occurrence: 9-19-13, time unknown	Date and Hour of Discovery: 9-19-13 time 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The 3" poly line had a pin hole near a repair connection from a previous release.



Describe Area Affected and Cleanup Action Taken.* Some of the spill was contained inside the impervious containment, some of the spray area got outside the containment and affected an area previously impacted by a reportable spill at the same location on 9/9/13. Both spills are scheduled to be cleaned up in accordance with the NMOCD standards beginning on 11/18/13.

Please find the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: <u>[Signature]</u> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist		Approval Date: <u>5/5/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/>
Date: 1/27/14		Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-2072