


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources



Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-Big Sinks 19-24-31 USA #1 Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40261	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	19	24S	31E	140	North	1980	East	Eddy

Latitude 32.209878 Longitude 103.81927

#### NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release 10 bbls crude oil and 68 bbls produced water	Volume Recovered: 7 bbls crude oil and 65 bbls produce water
Source of Release: Produced water tank	Date and Hour of Occurrence Date 12/4/13 time unknown	Date and Hour of Discovery 12/4/13 at 1:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and BLM	
By Whom? Tony Savoie	Date and Hour 12/4/13 at 3:337 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The well had just been put back on production, due to no casing gas pressure to operate the vessels the production was turned in the SWD tanks, the well unloaded causing the water tanks to overflow out of the hatches and enerdo valve. The well was switched back into normal operations.

Describe Area Affected and Cleanup Action Taken.\*  
Most of the spill was contained with the 0 perm containment around the tanks, due to high winds; approximately 70,000 sq. ft. of pasture was misted with Emulsion out of the tanks. The spill also ponded up in an area covering about 2000 sq. ft outside the containment walls. A vacuum truck was used to pick up all of the free standing fluid and a power washer was used to wash down the most heavily impacted vegetation. The impacted area will be remediated in accordance to the NMOCD and BLM remediation guidelines. The impacted area will be remediated in accordance to the NMOCD and BLM spill Guidelines.

Approximately 520 cu. yds of impacted soil was excavated from an area measuring approximately 20' to 40' in width, 150' in length, and 18" to 2.5' in depth. Impacted soil was hauled to an NMOCD-approved disposal facility and confirmation soil samples were collected on approximate 50' intervals. **Please reference the attached Remediation Summary and Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: 5/15/14	Expiration Date: MA
E-mail Address: tasavoie@basspet.com		Conditions of Approval: <i>Final</i>	
Date: 5/9/14		Attached <input type="checkbox"/>	
Phone: 432-556-8730			

\* Attach Additional Sheets If Necessary

2RP-2103