


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1700 Rio Brazos Road, Aztec, NM 87410  
District IV  
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nHMP1412226568

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Dodd Federal Unit #110	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#) 30-015-35139	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	29E					Eddy

Latitude 32.82827 Longitude 104.05744

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	24bbbs	Volume Recovered	22bbbs
Source of Release	Steel line	Date and Hour of Occurrence	04-07-2014	Date and Hour of Discovery	04-07-2014 08:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A steel line going to the FWKO developed a hole due to age. The steel line has been replaced and is in operation.

Describe Area Affected and Cleanup Action Taken.\*

Initially 24bbbs of produced water were released. We were able to recover 22bbbs of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:		Approved by District Supervisor:		
Printed Name:	Robert Grubbs Jr.	Approval Date:	5/2/14	Expiration Date:
Title:	Senior Environmental Coordinator	Conditions of Approval:		
E-mail Address:	rgrubbs@concho.com	Attached <input type="checkbox"/>		
Date:	04-22-2014	Phone: 432-661-6601		

*Final*

\* Attach Additional Sheets If Necessary

22P-2281