

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Revision State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 15 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Long Draw 10 E Federal #1	Facility Type: Producing Oil Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-36879

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 20S	Range 25E	Feet from the 2310'	North/South Line North	Feet from the 990'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.588808 Longitude -104.478037

NATURE OF RELEASE

Type of Release: Oil(9 bbls)	Volume of Release: 9 bbls	Volume Recovered: 8 bbls
Source of Release: Oil Well	Date and Hour of Occurrence 5-13-14	Date and Hour of Discovery 5-13-14 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Ricky Apperson	Date and Hour 3-27-14 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Thief hatch was left open on oil tank allowing oil to spill into containment.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Inside the containment.

Cleanup- Called vacuum truck to come pick up standing fluid from inside the containment (a total of 8 bbls were recovered and taken to Tweedy SWD). got pressure washer to clean off tanks and cat walk. Also backhoe will dig out contaminated soil inside containment and haul off to R360 and clean caliche will be used to backfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: 6/13/14	Expiration Date: NA
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/13/14	
Date: 5-15-14 Phone: 575-602-2188	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

RP-2311