

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #55 (2RP-1177)	Facility Type: E & P

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27589
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter F	Section 17	Township 23S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-----------------

Latitude N 32.306285 Longitude W 103.801920

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 5 bbls of produced water and 3 bbls of crude oil	Volume Recovered: 3 bbls total fluid
Source of Release: Stuffing box on wellhead	Date and Hour of Occurrence: 5/18/12 Time unknown	Date and Hour of Discovery: 5/18/12 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Tony Savoie	Date and Hour	NM OIL CONSERVATION
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

JUL 01 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.* The packing in the stuffing box failed. The packing was replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 410 sq. ft. of caliche well pad. All of the free product was removed with a vacuum truck, the stained soil was left in place pending remediation activities that will follow the NMOCD and BLM guidelines for leak and spills.

Approximately 740 cu. yds of impacted soil was excavated from an area measuring approximately 12' to 30' in width, 130' in length, and 2' to 4' in depth. Impacted soil was hauled to an NMOCD-approved disposal facility. **Please reference the attached Remediation Summary and Risk-Based Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: 7/2/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval: <i>Final</i>	
Date: 7/1/14 Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary