

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Remuda Basin Battery #1 (2RP-1458)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-03691	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
I	24	23S	29E					

Latitude N 32.288041 Longitude W 103.936333

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Unknown truck unauthorized release	Date and Hour of Occurrence: Date and hour unknown	Date and Hour of Discovery: 11/26/12 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 11/26/12 at 10:22 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **NM OIL CONSERVATION**
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.* **JUL 01 2014**
The spill was caused by an un-authorized release on the well pad location.

Describe Area Affected and Cleanup Action Taken.* **RECEIVED**
Well pad location, drilling reserve pit, and pasture land. No cleanup has been initiate pending investigation at the site. The affected area in the pasture will be remediated in accordance to the NMOCD Guidelines.
Approximately 4,440 cu. yds of impacted soil was excavated from the affected well pad location. Impacted soil was hauled to an NMOCD-approved disposal facility. During the remediation of the affected well pad, a historic drilling reserve pit north of the release site was also reclaimed. **Please reference the attached Remediation Summary and Risk-Based Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 7/2/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 4/9/14 7/1/14	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary