Submit 3 Copies To Appropriate District Office	State of N	ew Mexico		Form C-103 October 25, 2005
			WELL API NO.	
1625 N. French DE Hobos FNM 88240 D			30-015	5-21825
District III			5. Indicate Type of Lease	
Distict III 1000 Rio Brazostra AZEO, ANBYEMINA 22		St. Francis Dr.	STATE 🖸	FEE
District IV Santa Fe, NM 87505			6. State Oil & Gas Lease	No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIV	ED			
	ND REPORTS ON WE	LLS	7. Lease Name or Unit A	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			Empire	Abo Unit
A DIFFERENT RESERVIOR. USE "APPLIC PROPOSALS.)	8. Well Number			
1. Type of Well: Oil Well 🔽 Gas Well	Other		1	52
2. Name of Operator	0		9. OGRID Number	79
3. Address of Operator	· · · ·	873		
303 Veterans Airpark Ln.	, Ste. 3000, Midland, T	X, 79705	Empir	e Abo
4. Well Location		E "		C line
Unit Letter O : Section 2	2602feet from theTownship18S	E line and Range 27E	320 feet from the NMPM	S line County Eddy
	Elevation (Show whether	<u>U</u>		A A A A A A A A A A A A A A A A A A A
	3	568' GR	ka san ang mata ng	در . <u>مربع بالمحمد مربع مالام مربع مالام المربع المربع المربع المربع المربع الم</u>
12. Check Appropriate Box To Indicate	Nature of Notice, Repor	rt, or Other Data		
	G AND ABANDON	REMEDIAL WORK		
		COMMENCE DRILLING OF		
PULL OR ALTER CASING		CASING/CEMENT JOB		
		The Central	Valley Elect. to remove fu	Coop. has
OTHER:		Location is r	eady for OCD inspection a	fter P&A
 All pits have been remediated in compliance Rat hole and cellar have been filled and level 				
A steel marker at least 4" in diameter and a	-			
OPERATOR NAME, LEASE				
UNIT LETTER, SECTION, T				
PERMANENTLY STAMPED				
The location has been leveled as nearly as	possible to the original groun	d contour and has been clea	red of all junk, trash, flow lin	ies and
other production equipment.			····	
 Anchors, dead men, tie downs and risers have a series of the series of th		-	nediated in compliance with	
OCD rules and the terms of the Operator's				
from the lease and well location.	Destable bases	have been serviced (David	d and the second because do	net here
 All metal bolts and other materials have been to be removed.) 	in removed. Portable bases	have been removed. (Poure	a onsite concrete bases do	not nave
All other environmental concrens have been	•			
Pipelines and flow lines have been abandor non-retrieved flow lines and pipelines.	red in accordance with 19.15	.9.714.B(4)(b) NMAC. All flu	ids have been removed from	1
When all work has been completed, return t				
inspection has to be made to a R&A locatio	n because it does not meet tr	ne criteria above, a penaity n	hay be assessed.	
SIGNATURE ZON SUMME	TITLE	P&A Tech	DATE	5/16/14
	lloro	loon collora@onoch		422 209 0240
TYPE OR PRINT NAME Leon Se	11010	leon.sellers@apache	ecorp.com PHONE:	432-208-0349
· •	I TITLE	1 0		7/0/0
APPROVED BY: Conditions of Approval (if any):	UK 70 KEZ	J. O.	DATE	118114
	14-0 0-	1 mars		
	OF TO KEL	Lense.		

っと	70	RELEASE