

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n HMP 14/9931221

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: Bass 3 Federal #4		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner: Federal	
		API No. 30-015-28736	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	3	22S	28E	1980	South	330	East	Eddy

Latitude N 32.420218 Longitude W 104.067417

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 1 bbl oil and 8 bbls PW water	Volume Recovered: None
Source of Release: Pump Jack stuffing box packing	Date and Hour of Occurrence: 6/22/14 time unknown	Date and Hour of Discovery: 6/22/14 at approximately 11:20 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 10 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
The stuffing box packing failed releasing the fluid. The pump jack was equipped with an E-Pot designed to contain and shut down the pumping unit in the event of a release. The E-pot had been damaged and did not operate properly. The packing was replaced and the E-pot was replaced and tested on 6/23/14.

Describe Area Affected and Cleanup Action Taken.*
The release impacted approximately 1100 sq.ft. of caliche well pad. All of the fluid soaked into the ground and has been left as is until the area can be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>7/10/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoic@basspet.com</i>		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Date: 7/10/14	Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

8/18/14

ZRP-2371