

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1419935641

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie		
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329		
Facility Name: Poker Lake Unit 227 Tank Battery	Facility Type: Exploration and Production		
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-33929	

LOCATION OF RELEASE

Unit Letter P	Section 30	Township 24S	Range 30E	Feet from the 330	North/South Line South	Feet from the 560	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.181934 Longitude W 103.913878

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: Process separator	Date and Hour of Occurrence: 7/3/14 time unknown	Date and Hour of Discovery: 7/3/14 at approximately 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION
ARTESIA DISTRICT**

JUL 10 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
Cows broke a 1/4" fitting off of one of the process separators. The fitting was replaced and a fence was installed around the process equipment.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 350 sq.ft. of caliche pad. The free standing fluid was recovered, the stained soil was left as is pending remediation. The area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>7/18/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 7/10/14 Phone: 432-556-8730	<i>8/18/14</i>	<i>22P-2373</i>

* Attach Additional Sheets If Necessary