


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHmp 1420232194

OPERATOR Initial Report Final Report

Name of Company COG OPERATING LLC <i>229137</i>	Contact Robert McNeill
Address 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name SRO State Com #5H	Facility Type Well

Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-37425
---------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 8	Township 26S	Range 28E	Feet from the 660	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude *32.051544* Longitude *104.11708*
NATURE OF RELEASE

Type of Release Produced water and Condensate	Volume of Release Unknown (bbls)	Volume Recovered Unknown (bbls)
Source of Release Well Control Issue	Date and Hour of Occurrence 07-01-2014 2:30 pm	Date and Hour of Discovery 07-01-2014 2:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade - NMOCD	
By Whom? Amanda Trujillo	Date and Hour 07-02-2014 09:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
During a routine pump change, while pulling tubing, the well kicked, and the BOP rams were unable to close around the tubing. A third party well service company addressed the issue. During the event fluid being releases was a light mist. All free standing fluids picked up and disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*
Main impact area was contained to the pad. Berms were constructed to control any runoff. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: 07-10-2014 Phone: 575-748-6940	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
8/21/14 *2RP-2383*