

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 21 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

NA81420529940 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Gissler Federal #13H	Facility Type	Battery

Surface Owner : Federal Mineral Owner : Federal Lease No. (API#) 30-015-38121

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	5	17S	30E	1650	South	330	West	Eddy

Latitude *32.86096295* Longitude *104.001732887*

NATURE OF RELEASE

Type of Release	Produced water and Condensate	Volume of Release	30 bbls Oil; 15 bbls PW	Volume Recovered	28 bbls Oil; 12 bbls PW
Source of Release	Heater treater inside battery	Date and Hour of Occurrence	07-09-2014 11:00 pm	Date and Hour of Discovery	07-09-2014 11:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher -- NMOCD/Jeffery Robertson -- BLM		
By Whom?	Amanda Trujillo	Date and Hour	07-11-2014 05:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Gasket on the lower manway of the heater treater ruptured causing fluid to spray from the vessel. All free standing fluids picked up and disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*
Main impact area was contained within the bermed area. An area approximately 115' x 25' found directly behind the separating equipment received heavier impact. Adjacent to this area is a 335' x 180' area which is low impact spray area. All free fluids have been recovered. COG will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/24/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: remediation per OGD rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 07-21-2014 Phone: 575-748-6940	PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

8/24/14 **2 RP-2389**