

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP141994515

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Devon Energy Production <i>6137</i>	Contact	Mike McMahan
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575.706.4165
Facility Name	Josey Wales 16 State Com 3H	Facility Type	Oil
Surface Owner State	Mineral Owner State	API No. 30-015-41090	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	24S	27E	150	S	1980	E	EDDY

Latitude: Longitude:

NATURE OF RELEASE

Type of Release Spill	Produced Water	Volume of Release	15 BBL	Volume Recovered	10 BBL
Source of Release	Back pressure valve failed	Date and Hour of Occurrence	7.11.14 9:00 AM	Date and Hour of Discovery	7.11.14 9:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos BLM & Laura OCD- left message		
By Whom?	Mike McMahan	Date and Hour	7.11.14 9:30 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
July 11, 2014 @ 8:00a.m at the Josey Wales 16 State Com #3H location lease operator noticed a spill of 15 bbls. All of produced water due to a check valve failure.

Describe Area Affected and Cleanup Action Taken.*
On July 10, 2014 at the Josey Wales 16 State Com #3H lease operator disconnected the compressor and disconnected all the lines from the unit. The drain line from the unit is connected to the production water line and there was a bad check valve on the line, causing a spill of 15 bbls. produced water. A vacuum truck was called out and contractor was able to recovered 10 bbls. All appropriate notifications were made and calls to the appropriate personal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist:	<i>[Signature]</i>
Title: Field Admin Support	Approval Date: <i>7/28/14</i>	Expiration Date: <i>NA</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7.11.14 Phone: 575.748.	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
8/28/14

L CONSERVATION
RTESTA DISTRICT
2PP-2376
JUL 14 2014

RECEIVED