

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1424536124

Name of Company: BOPCO, L.P. <i>260737</i>	OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Contact: Tony Savoie
Facility Name: PLU-CVX-JV-BS #002H Formerly PLU-Big Sinks 11 #1H	Telephone No. 575-887-7329
	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-37147
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	11	24S	30E	255	South	1300	East	Eddy

Latitude N 32.225692 Longitude W 103.846708

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 20 bbls.	Volume Recovered: 10 bbls.
Source of Release: 2" check valve	Date and Hour of Occurrence: 8/14/14 time unknown	Date and Hour of Discovery: 8/14/14 at 1:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 8/14/14 at 1:45 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
SEP 02 2014

Describe Cause of Problem and Remedial Action Taken.*

A check valve failed on the lact unit diverting line due to a closed valve on the tank. The check valve was replaced. **RECEIVED**

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 3090 sq. ft. of caliche well pad. The free standing fluid was recovered with a vacuum truck and the saturated soil was scraped up. Approximately 16 cubic yards of soil was hauled to Lea Lands by EPI.
The final remediation will comply with the NMOCD and BLM spill remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>9/2/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	
Date: 9/2/14	Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

10/2/14

2RP-246A