District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Fran	icis Dr., Sant	a Fe, NM 8750:	5	S	Santa Fe, NM 87505							side of form	
Release Notification and Corrective Action													
OPERATOR Initial Report X Fina												Final Report	
Name of Company Oxy Permian Ltd.							Contact Christopher Jones						
	1502 Ŵ. C	Telephone No. (575) 628-4121											
Facility Nar		Facility Type Production											
Surface Our	ner BIM	API No. 30-015-34272											
Surface Owner BLM Mineral Owner							AFTINO. 30-015-34272						
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North	n/South Line Feet from the East/West Line		est Line	County				
Н	13	22S	24E	840		South	1650 ·	E	East	Eddy Cou	nty, NN	1	
Latitude Longitude													
······································													
NATURE OF RELEASE Type of Release Produced water Volume of Release 80 bbls Volume Recovered 0 bbls													
Source of Release Steel flow line						Volume of Release 80 bbls Date and Hour of Occurrence			Volume Recovered 0 bbls Date and Hour of Discovery				
Source of Release Sicer now fine						Date and Hour of Occurrence			02/06/2010 @ 7:00 ain				
Was Immedia	ate Notice C	If YES, To Whom?											
Yes 🗌 No 🗍 Not Required Randy Dade-NMOCD, I									BLM				
By Whom? Rick Kerby- HES Oxy							Date and Hour See above						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
\Box Yes \boxtimes No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
Steel flow line developed a hole.													
Describe Area Affected and Cleanup Action Taken.* Area affected was on and off of location to the east approx. 600 feet. Remediation was completed in accordance with the remediation plan approved by													
NMOCD via email 01/09/2014 and approved by Terry Gregston of the BLM via email on 11/08/2012.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations al	ly that the fill operators :	ntormation gi	ven above venort an	is true and comp	elease r	the best of my	knowledge and up	nderstan	d that pure	suant to NM	UCD ri may er	ties and danger	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their o	perations h	ave failed to a	dequately	investigate and r	emediat	te contaminati	on that pose a three	eat to gre	ound water	. surface wa	ter, hu	man health	
or the environ	ment. In a	dinon NMO	CD accep	tance of a C-141	report d	loes not reliev	e the operator of t	responsil	oility for c	ompliance v	vith any	v other	
federal, state, or local laws prid/or regulations.													
							OIL CONSERVATION DIVISION						
Signature:	\mathcal{P}	\mathbb{X}		<u> </u>									
Printed Name	: Christo	Approved by District Supervisor:											
76/1/ 111													
Title: HES	Specialist	·	Approval Date: 7/22/14 Expiration Date:										
E-mail Address: Christopher Jones@oxy.com							Conditions of Approval:						
11	1 22)	Finel Attached										
Date: 71	<u>8/14</u>		Phone:	(575) 628-412	1		V~ 1	ne	K				

* Attach Additional Sheets If Necessary

- AL