

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141  
Revised October 10, 2003

SEP 24 2014  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

**0AB1424854825** **209384** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly A Inj Plant (Skelly # 41)	Facility Type: Water Flood

Surface Owner: Federal	Mineral Owner:	API No.: (closest well 3001505343)
------------------------	----------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	17S	31E	330	North	330	East	Eddy

Latitude: 32.8264443770721 Longitude: -103.85001508143

NATURE OF RELEASE



Type of Release: Produced Water / Oil	Volume of Release: 50 bbls / 1 gal	Volume Recovered: 30 / .5 gal
Source of Release: 3" Steel line	Date and Hour of Occurrence: 07/16/2014	Date and Hour of Discovery: 07/16/2014 8:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson- BLM Mike Bratcher- NMOCD	
By Whom? Brian Wall	Date and Hour 07/17/2014 0650	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: 3" steel transfer line leading from injection header toward Satellite 1 eroded and leaked into its dike between 2 AM and 8 AM this morning.

Describe Area Affected and Cleanup Action Taken.\* : The dike was standing about 4-6" deep over a distance of 12' x 25'. Because it was an injection line, there was very little oil involved.  
Directions to site: From intersection of Hwy 82 and 529, turn east on 82, go 2.2 miles, turn north for .6 miles, location on left

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Brian Wall		Approved by District Supervisor: 	
Title: Construction Foreman II		Approval Date: 7/25/14	Expiration Date: N/A
E-mail Address: bwall@linenergy.com		Conditions of Approval:	
Date: 07/17/2014 Phone: 806-367-0645		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 10/25/14

2RP-2515