

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Lost Tank 10 Federal #2	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-37960

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	22S	31E	840	South	1838	East	Eddy

Latitude N 32.415595°

Longitude W 103.763146°

#### NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	10 bbls oil, 5 bbls produced water	Volume Recovered	0 bbls
Source of Release	4" needle valve on circulating line broke off	Date and Hour of Occurrence	10/01/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Chancey Summers	Date and Hour	10/07/2013 @ 10:14 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**  
 MAY 23 2014  
 NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*

Area livestock have been rubbing the circulating line causing the 4" needle valve to break off and allow 10 bbls of oil and 5 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was approximately 20' x 40' with all of the leak staying on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher in a meeting on 02/19/2014 and approved by Jennifer Van Curen of the BLM via email on 02/24/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Specialist	Approval Date: 8/13/14	Expiration Date: NA	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: Final		Attached <input type="checkbox"/>
Date: 5-19-14	Phone: (575) 397-8216		

\* Attach Additional Sheets If Necessary

22P-1996