

SEP 25 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit a Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report




Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Bass 3 Federal #4 (2RP-2371)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-28736	

LOCATION OF RELEASE

Unit Letter 1	Section 3	Township 22S	Range 28E	Feet from the 1980	North/South Line South	Feet from the 330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.420218 Longitude W 104.067417

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 1 bbl oil and 8 bbls PW water	Volume Recovered: None
Source of Release: Pump Jack stuffing box packing	Date and Hour of Occurrence: 6/22/14 time unknown	Date and Hour of Discovery: 6/22/14 at approximately 11:20 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The stuffing box packing failed releasing the fluid. The pump jack was equipped with an E-Pot designed to contain and shut down the pumping unit in the event of a release. The E-pot had been damaged and did not operate properly. The packing was replaced and the E-pot was replaced and tested on 6/23/14.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 1100 sq.ft. of caliche well pad. All of the fluid soaked into the ground and has been left as is until the area can be cleaned up in accordance to the NMOCD and BLM remediation guidelines. Basin Environmental began the spill remediation on 8/6/14, a work plan defining the remediation objective and re-closure of a reserve pit was submitted prior to backfilling the site. The dirt work was completed on 9/10/14, approximately 1680 cubic yards of soil was hauled to Lea Land. Reference the Site Closure Report dated September 2014.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Tony Savoie		Approved by Environmental Specialist: 
Title: Waste Management and Remediation Specialist		Approval Date: 9/29/14 Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval:  Attached <input type="checkbox"/>
Date: 9/25/14 Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

2RP-2371