

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 08 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428130417

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: BEU-DI-9 #34H (Frac spill at the JRU-29 SWD)	Facility Type: Exploration and Production
Surface Owner: State	Mineral Owner: State
API No. 30-015-27735	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	22S	30E	1980	South	2310	West	Eddy

Latitude N 32.346280 Longitude W 103.835916

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 220 bbls	Volume Recovered: 198 bbls
Source of Release: 10" lay flat hose to pump connection from the JRU-29 SWD to the BEU-DI-9 #34H frac	Date and Hour of Occurrence: 9/30/14 at 7:45 p.m.	Date and Hour of Discovery: 9/30/14 at 7:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson (voice mail)	
By Whom? Tony Savoie	Date and Hour: 10/1/14 at approximately 9:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A flange connection from the frac hose to the water transfer pump broke. The water transfer pump was shut down until the broken flange could be replaced.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 12,476 sq.ft. of pasture. All of the free standing fluid was recovered with vacuum trucks. Basin Environmental collected soil samples throughout the pond area on 10/2/14 to help determine the amount of PW lost in the soil. BOPCO is in the process of obtaining permission from the State Land Office to access and remediate the area. The area will be cleaned up in accordance to the NMOCD remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>10/8/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	
Date: <i>10/7/14</i>	Remediation per O.C.D. Rules & Guidelines	
Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: *11/5/14*

2 RP-2525