

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

1 AB 1427652864

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Willow State #4	Facility Type: Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-21844
----------------------	----------------------	----------------------

LOCATION OF RELEASE

30-015-32844

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	17S	31E	1190'	South	330'	East	Eddy

Latitude 32.8305986298119 Longitude -103.867227754648

NATURE OF RELEASE

Type of Release: Oil and PW	Volume of Release: 7 bbls Oil ; 7 bbls PW	Volume Recovered: 3 bbls Oil ; 3 bbls PW
Source of Release: Wellhead	Date and Hour of Occurrence: 9/23/2014 7:00 am	Date and Hour of Discovery: 9/23/2014 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A quarter inch nipple was broken off the wellhead by a cow rubbing up against the wellhead. A vacuum truck was dispatched to recover any standing fluid and the location was scraped.

Describe Area Affected and Cleanup Action Taken.*
The impacted area was approximately 100'x400', the area was scraped and treated with Microblaze. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Brannon</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>10/3/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 2, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: *11/3/14*

2RP-2521