

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised October 10, 2003  
OCT 10 2014 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form  
**RECEIVED**

**Release Notification and Corrective Action**

11AB1428740298 OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 28 Federal #1 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-26194	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27336° Longitude W 103.78031°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	67 bbls	Volume Recovered	0 bbls
Source of Release	Nipple on discharge header at the east injection pump was off	Date and Hour of Occurrence	10/06/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, Sol Hughes-BLM		
By Whom?	Kathy Purvis @ BBC International, Inc.	Date and Hour	10/07/2014 @ 11:46 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The nipple on the discharge header at the east injection pump was off allowing 67 bbls of produced water to leak onto the ground. No fluids were recovered and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 50' x 100' on location and 10' x 100' off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by District Supervisor: 
Printed Name: Chancey Summers	Approval Date: <u>10/14/14</u> Expiration Date: <u>NA</u>
Title: HES Advisor	Conditions of Approval:
E-mail Address: Chancey.Summers@oxy.com	Remediation per O.C.D. Rules & Guidelines
Date: <u>10-10-14</u> Phone: (575) 397-8216	Attached <input type="checkbox"/>

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/14/14**

\* Attach Additional Sheets If Necessary

2RP-2546