

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 20 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1429431024

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC #229137

Contact: Robert McNeill

Address: 600 West Illinois Avenue, Midland TX 79701

Telephone No. 432-230-0077

Facility Name: Honey Graham State Com #1H

Facility Type: Battery

Surface Owner: State

Mineral Owner: State

API No. 30-015-37465

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	26S	28E	330	North	660	West	Eddy

Latitude 32.018610330935 Longitude -104.11702930695

### NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 353 bbls Oil ; 60 bbls PW	Volume Recovered: 0 bbls Oil ; 0 bbls PW
Source of Release: Flood damaged battery	Date and Hour of Occurrence: 9/19/2014	Date and Hour of Discovery: 10-6-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am (phone call)	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	

If a Watercourse was Impacted, Describe Fully.\*



Torrential rains caused flood waters to rise. Waters over ran the location, broke tank drain lines. This location was inaccessible for several weeks.

Describe Cause of Problem and Remedial Action Taken.\*

Describe Area Affected and Cleanup Action Taken.\*

The impacted area shows no signs of hydrocarbon or brine impact. Once the area dries out and is accessible to heavy equipment we will conduct a more thorough search of the area for hydrocarbon impact. Equipment will be removed from the draw and disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 10/21/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 20, 2014	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 11/21/14

2RP-2559