

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NOV 04 2014

Form C-141  
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1430856630

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Dorado 34 DA Fed Com #111	Facility Type: Oil producing Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-41394
--------------------	--------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	34	18S	30E	405'	North	321'	West	Eddy

Latitude 32.710104 Longitude -103.9673628

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: estimated 70 bbls total fluid	Volume Recovered: Oil (60 bbls)
Source of Release: Oil tank's load line	Date and Hour of Occurrence 11-1-14	Date and Hour of Discovery 11-1-14 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Eddy County Sherriff Department	
By Whom? Jaime Hobbs	Date and Hour 11-1-14 5:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause of the leak- Load line seals on every oil tank were cut and valves were opened including main load line for oil trucks, releasing an estimated 70 bbls of oil on pad surface directly outside secondary containment. Upon discovery, main load line was shut in order to stop the release.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- Pad surface in between pumping unit and secondary containment. JWS vacuum trucks were used to recover 60 bbls of oil off pad surface. All contaminated soil will be removed and disposed at an approved NMOCD disposal site. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Z. Thomas</u>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Signed By <u>M. L. Brown</u>	
Title: Environmental Rep.	Approved by Environmental Specialist:	
E-mail Address: zthomas@mewbourne.com	Approval Date: 11/4/14	Expiration Date: N/A
Date: 11-3-14	Conditions of Approval:	Attached <input type="checkbox"/>
Phone: 575-602-2188	Remediation per O.C.D. Rules & Guidelines	
	SUBMIT REMEDIATION PROPOSAL NO	
	LATER THAN: 12/4/14	

2RP-2575