

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 05 2014 Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1431051803

OPERATOR

Initial Report Final Report

Name of Company: Apache Corporation <i>873</i>	Contact Bruce Baker
Address: 2350 W Marland BVL D Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name EL Federal #3 <i>E L Federal #3</i>	Facility Type: Oil Well (P/A)

Surface Owner BLM	Mineral Owner	API No. 30-015-36662
-------------------	---------------	---------------------------------

LOCATION OF RELEASE

30-015-30257

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	21	17S	30E	1700'	FNL	1050'	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: produced water	Volume of Release 10 barrels of produced water	Volume Recovered None
Source of Release: flow line	Date and Hour of Occurrence 11/3/2014 at 8:00 a.m.	Date and Hour of Discovery 11/3/2014 at 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message with Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date and Hour 11/4/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flow line was buried under the lease road and a dozier operator engaged the rippers while driving down the lease road causing the line to rupture. The line was shut in and repaired.

Describe Area Affected and Cleanup Action Taken.*
The release affected the lease road and the pasture area north and south of the lease road. The release area was mapped and the site will be remediated to NMOCD and BLM regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Signed By <i>Mike Deane</i>	
Title: Environmental Technician	Approved by Environmental Specialist:	
E-mail Address: larry.baker@apachecorp.com	Approval Date: <i>11/6/14</i>	Expiration Date:
Date: 11/5/14	Phone: (432) 631-6982	Attached: <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *12/6/14*

2012-2585