

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141

Revised June 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate

District Office in accordance

with Rule 116 on back

side of form.

30-015-04953

Release Notification and Corrective Action

OPERATOR

(revised) ☒ Initial Report ☐ Final Report

Name of Company	CBS Operating Corporation	Contact	M. A. Sirgo, III (Engineer)
Address	P.O. Box 2236 Midland, TX 79702	Telephone No.	432-685-0878
Facility Name	North Square Lake Unit #160	Facility Type	Production Well and Battery

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NM081277
---------------	-----	---------------	-----	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from South Line	Feet from West Line	Longitude-W	Latitude-N	County
N	31	16S	31E	330	1357.4	103deg 54.740'	32deg 52.297'	Eddy

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water + Crude Oil Component	approximate 12 bbl	0 bbl
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Hole in casing @ Production Wellhead	11/12/2004	11/12/04 10:30 AM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Not Required	Paul Evans - BLM	
By Whom?	Date and Hour	
release discovered by Paul Evans		
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	NA	

If a Watercourse was Impacted, Describe Fully*

RECEIVED
 OCT 12 2005
 OCU-WH189A

Describe Cause of Problem and Remedial Action Taken. *

Hole developed in casing below wellhead. An emergency pit was dug to contain fluid. This pit was cleaned out and lined. During the next two weeks, the field became rain soaked and equipment could not get in location. 60-bbl, mostly rain water, was removed. Temporary pit was closed 12-01-04.

Describe Area Affected and Cleanup Action Taken. *

The area affected was the well pad around the pumping unit. Initial repair and clean-up as per attached Sundry. Ocotillo Environmental LLC, Hobbs, NM contracted (October-05) for remediation and site closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>M. A. Sirgo III</i>		OIL CONSERVATION DIVISION	
Printed Name:	M.A. Sirgo, III		TIM GUM	
Title:	Engineer		Approved by District Supervisor: <i>by MB</i>	
E-Mail Address:	mastres@aol.com		Approval Date: <i>10/21/05</i>	Expiration Date: <i>nila</i>
Date:	10/10/2005	Phone:	432-685-0878	Conditions of Approval:
				<input checked="" type="checkbox"/> Attached

Ocotillo



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

CBS Operating Corporation
PO Box 236
Midland TX 79702

October 21, 2005

Reference: North Square Lake Unit 160 N-31-16s-31e API: 30-015-04953

Operator,

The NMOCD District 2 Office (OCD) is in receipt of a work plan proposal for remediation of a produced fluids release that occurred at the above referenced well site on or about 11/12/2004. The work plan was formulated and submitted to the OCD by your agent, Ocotillo Environmental.

The Remediation work plan is accepted as presented with the following stipulations:

1. Notify the OCD District 2 office 24 hours prior to commencement of remediation activities.
2. Notify the OCD District 2 office 24 hours prior to obtaining samples where analysis of samples obtained are to be presented to the OCD.
3. Any contaminated soils removed from location must be transported to an approved OCD disposal facility.
4. Submit a Final Report C-141 along with any confirmation sample analysis, upon satisfactory completion of project.
5. Like approval by BLM if applicable.
6. Remediation work is to commence no later than November 7, 2005.

Please be advised that NMOCD acceptance or approval of documents and/or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance or approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

If I can be of assistance in this matter, and for notification of activities, my contact information is listed below.

Thank you,

Mike Bratcher

NMOCD District 2

1301 W Grand Ave.

Artesia, NM 88210

(505) 748-1283 Ext 108

(505) 626-0857

Mike.Bratcher@state.nm.us