

# NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 14 2014 Form C-141  
Revised October 10, 2003

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

NAB1432234636 OXY USA INC. OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 28 Federal #1 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-26194

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27336° Longitude W 103.78031°

## NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	22 bbls	Volume Recovered	0 bbls
Source of Release	Nipple on discharge header at the west injection pump was off	Date and Hour of Occurrence	10/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD, Sol Hughes-BLM		
By Whom?	Kathy Purvis @ BBC International, Inc.	Date and Hour	10/24/2014 @ 8:39 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The nipple on the discharge header at the west injection pump was off allowing 22 bbls of produced water to leak onto the ground. No fluids were recovered and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 12' x 100' on location and 5' x 100' off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Title: HES Advisor

E-mail Address: Chancey.Summers@oxy.com

Date: 11-13-14

Phone: (575) 397-8216

Signed By Mike Bratcher  
Approved by District Supervisor:

Approval Date: 11/18/14

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines

Attached ☐

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/18/14

2RP-2601

\* Attach Additional Sheets If Necessary