

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1432328337

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company <b>Devon Energy</b>	Contact <b>Jaime Castillo</b>
Address <b>PO Box 250 Artesia, NM 88211</b>	Telephone No. <b>575-746-5575</b>
Facility Name <b>Rigel 20 Fed Com 3H</b>	Facility Type <b>Oil</b>
Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>
API No. <b>3001539725</b>	

**LOCATION OF RELEASE**

Unit Letter <b>L</b>	Section <b>20</b>	Township <b>19 S</b>	Range <b>31 E</b>	Feet from the <b>1800</b>	North/South Line <b>FSL</b>	Feet from the <b>330</b>	East/West Line <b>FWL</b>	County <b>Eddy</b>
-------------------------	----------------------	-------------------------	----------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	-----------------------

Latitude: 32.6435781 N

Longitude: 103.8989164 W

**NATURE OF RELEASE**

Type of Release <b>Air release/ gas</b>	Volume of Release <b>220 mcf</b>	Volume Recovered <b>0- vented</b>
Source of Release <b>separator</b>	Date and Hour of Occurrence <b>March 18, 2014 AM</b>	Date and Hour of Discovery <b>March 18, 2014 8:15 AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher</b>	
By Whom? <b>Randy Gladden</b>	Date and Hour <b>March 24, 2014 1:30 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	
If a Watercourse was Impacted, Describe Fully.* <b>N/A</b>		
Describe Cause of Problem and Remedial Action Taken.* DCP sales line pressurized which shut the slam valve on the DCP line causing the Devon separator to become pressurized which caused release to the vent tank. Slam valve has been re-opened.		
Describe Area Affected and Cleanup Action Taken.* Atmosphere surrounding location. N/A		

RECEIVED

MAR 26 2014

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Sandra Farley</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Sandra Farley</b>	Signed By <b>Mike Bratcher</b>	
Title: <b>Field Admin Support</b>	Approved by Environmental Specialist:	
E-mail Address: <b>Sandy.Farley@dvn.com</b>	Approval Date: <b>11/18/14</b>	Expiration Date: <b>N/A</b>
Date: <b>March 24, 2014</b>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Phone: <b>575.746.5587</b>		

\* Attach Additional Sheets If Necessary

2RP-2606