

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1432439096		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Tony Savoie		
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329		
Facility Name: PLU-JV-CVX-Big Sinks #017H		Facility Type: Exploration and Production		
AKA PLU Big Sinks 7-25-31 USA #1H				

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40447
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 7	Township 25S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.151692 Longitude W 103.819416

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 26 bbls. crude oil	Volume Recovered: 7 bbls
Source of Release: Flare stack	Date and Hour of Occurrence: 11/16/14 time unknown	Date and Hour of Discovery: 11/16/14 at approximately 1:39 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson, and Jim Amos BLM Via e-mail	
By Whom? Tony Savoie	Date and Hour: 11/16/14 at 4:12 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT

If a Watercourse was Impacted, Describe Fully.*

NOV 18 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

The flare stack motor valve and scrubber float valve failed to operate properly causing fluid to go out the flare stack. The system was repaired

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 2550 sq.ft. of pasture land that had been recently disturbed during a pipeline construction job. The release also misted approximately 4760 sq.ft. of pasture area. All of the free standing fluid was recovered; the stained area was left as is pending remediation. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: M. Bratcher Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist		Approval Date: 11/19/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/18/14	Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 12/19/14	

* Attach Additional Sheets If Necessary

2RP-2613