

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 14 2014

Form C-141
Revised October 10, 2003

RECEIVED
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NAB1432250434

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 11/6/96	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Cypress 33 Federal #6H	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-41557
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E	466	North	1040	East	Eddy

Latitude N 32.26685° Longitude W 103.98463°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Excess pressure caused the stuffing box packing on the well head to blow off	Date and Hour of Occurrence	11/06/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Sol Hughes-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	11/07/2014 @ 9:42 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Excess pressure caused the stuffing box packing on the well head to blow off and leak 10 bbls of oil onto the ground. No fluids were recovered and the stuffing box packing was replaced.


Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 50' x 150' on location. Remediation will be completed in accordance a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:



Printed Name: Chancey Summers

Signed By 
Approved by District Supervisor:

Title: HES Specialist

Approval Date: 11/18/14

Expiration Date:

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval:

Attached ☐

Date: 11/13/14 Phone: (575) 397-8216

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/18/14

2RP-2603

* Attach Additional Sheets If Necessary