

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1432355958 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit DI-9 Tank Battery (Vessel for #34H)	Facility Type: Exploration and Production
Surface Owner: State	Mineral Owner: State and Federal
API No. 30-015-42008	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
P	21	21S	30E					Eddy

Latitude N 32.456585 Longitude W 103.879241

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 46 bbls crude oil and 18 bbls produced water	Volume Recovered: 26 bbls crude oil and 10 bbls produced water
Source of Release: Heater-treater	Date and Hour of Occurrence: 11/7/14 at approx. 8:00 p.m.	Date and Hour of Discovery: 11/7/14 at approx. 9:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher and H. Patterson (via e-mail)	
By Whom? Tony Savoie	Date and Hour: 11/8/14 at 2:51 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 18 2014

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A gasket failed on the heater-treater man-way plate. The well was shut in and the gasket was replaced. All free standing fluid was removed with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 6,750 sq.ft. of process containment area that had the base soil treated with a bionic soil solution during construction, samples were collected at 6" intervals to a depth of 3 ft. to check for oil and water saturation. The spill misted and area of approximately 3,425, sq. ft in the pasture. Soil samples were collected and field tested for chloride saturation depth in the pasture area. The lab results and soil chemistry tables are attached. The impacted area will be cleaned up in accordance to the NMOCD remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By <i>Mike Scanlon</i> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: <i>11/19/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	
Date: <i>11/18/14</i> Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>12/19/14</i>	

* Attach Additional Sheets If Necessary

2RP 2015