

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION Form C-141
ARTESIA DISTRICT Revised August 8, 2011
NOV 26 2014
Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

1 AB 1433049483

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. 2100737		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #120H		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-38116

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	8	23S	31E	290	South	1990	East	Eddy

Latitude N 32.312489 Longitude W 103.797380

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 3 bbls crude oil and 7 bbls produced water	Volume Recovered: None
Source of Release: a 2 7/8" flow line	Date and Hour of Occurrence: 11/21/14 time unknown	Date and Hour of Discovery: 11/21/14 at approximately 9:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The flow line developed a leak due to external corrosion. The well was shut in, the fluid in the line was removed with a vacuum truck and the section of line was replaced with externally coated flow line.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 1475 sq.ft. of caliche well pad. The oil and water had soaked into the ground. The saturated soil was scraped up with a backhoe and stockpiled on-site pending removal during the final site remediation. The impacted area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION Signed By: 11/19/14 [Signature]	
Printed Name: Tony Savoie	Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: 11/26/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 11/25/14	Phone: 432-556-8730	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Submit Remediation Proposal No. LATER THAN: 12/26/14

2RP-2029