

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JAN 26 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1503036865 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>8100737</u>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Bass #003W	Facility Type: SWD

Surface Owner: State	Mineral Owner: State	API No. 30-015-10442
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	12	19S	28E	2310	North	1650	West	Eddy

Latitude N 32.676043 Longitude W 104.133229

NATURE OF RELEASE

Type of Release: Production Fluids	Volume of Release: Unknown	Volume Recovered: Unknown
Source of Release: Production and SWD operations (Historical Spills)	Date and Hour of Occurrence: Date and time Unknown	Date and Hour of Discovery: 6/24/14 during final reclamation.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The well was P&A on 2/18/14, a crew started the final reclamation on 6/24/14 after the tanks and equipment had been removed. Heavily impacted soil was discovered around the production tanks and surrounding area.		
Describe Area Affected and Cleanup Action Taken.* The total affected area measured approximately 40,000 sq.ft. The investigation began with test trenches and finally ended up with the advancement of 5 soil bores across the impacted area. The sample results and final closure data will be presented with the Final C-141. The final reclamation was discussed with Mike Bratcher and given the spill report #2RP-2724.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: <u>[Signature]</u> Approved by Environmental Specialist	
Title: Waste Management and Remediation Specialist		Approval Date: <u>1/28/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>2/28/15</u>	
Date: <u>1/26/15</u> Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PAB1503036331

2RP-2724