

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

FEB 12 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB15047571028* OPERATOR  Initial Report  Final Report

Name of Company	RKIE&P, LLC <i>2410289</i>	Contact	Taylor Jones
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-996-5782
Facility Name	Ross Draw 14	Facility Type	Oil and Gas Well

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-25208
---------------	---------	---------------	---------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	30	26S	30E		2310 FSL		660 FWL	Eddy

Latitude 32.01211 Longitude -103.86465

**NATURE OF RELEASE**

Type of Release. Oil and Produced Water	Volume of Release 12 Bbbs	Volume Recovered 12Bbbs
Source of Release Wellhead packing	Date and Hour of Occurrence 02/11/15 - Unknown	Date and Hour of Discovery 02/12/15 - 0900hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Someone closed tubing and casing valves causing wellbore to pressure up and blow out packing. Well was Shut-in and repacked and placed back into production.

Describe Area Affected and Cleanup Action Taken.\*  
All fluid remained on well pad. Well was Shut-in and repacked and placed back into production; Vacuum truck dispatched to location to recover free fluids. Affected soil then dug and hauled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Taylor Jones</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Systems Specialist	Approval Date: <i>2/16/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: TJones@rkixp.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 02/12/2015	Phone: 405-996-5782	Attached <input type="checkbox"/>

SUBMIT REMEDIATION PROPOSAL NO. 2410289  
LATER THAN: 3/16/15

*2RP-2812*

\* Attach Additional Sheets If Necessary