

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

FEB 12 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

*NAB 1504838529*

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: COG Operating LLC	<i>329137</i>	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: Dirty Dozen State Com #3H		Facility Type: Wellhead	
Surface Owner: State	Mineral Owner:	API No. 30-015-38225	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	36	19S	31E	1810	South	720	East	Eddy

Latitude 32.6146940334203 Longitude -103.816411683419

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 25 bbls Oil ; 6 bbls PW	Volume Recovered: 20 bbls Oil ; 5 bbls PW
Source of Release: Wellhead	Date and Hour of Occurrence: 1/29/2015 7:00 am	Date and Hour of Discovery: 1/29/2015 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 5:37 pm	<i>1/30/15 5:37pm</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused when the wellhead pressured up and the packing failed to hold. Vacuum trucks were dispatched to pick up all standing fluids.

Describe Area Affected and Cleanup Action Taken.\*

This release was contained to the pad area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: <i>A. Trujillo</i>	Approved by Environmental Specialist: <i>[Signature]</i>
Printed Name: Amanda Trujillo	Approval Date: <i>2/17/15</i> Expiration Date:
Title: Senior Environmental Coordinator	Conditions of Approval:
E-mail Address: <i>atrujillo@concho.com</i>	Attached <input type="checkbox"/>
Date: February 12, 2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: *3/17/15*

*2RP. 2815*