

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB 19 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact: Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name: MJ SWD Line (near well EAU I-16 B)	Facility Type: Oil Well

Surface Owner State	Mineral Owner	API No. 30-15-00724
---------------------	---------------	---------------------

### LOCATION OF RELEASE

Unit Letter A	Section 2	Township 18S	Range 27E	Feet from the 990'	North/South Line FNL	Feet from the 330'	East/West Line FEL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude N324647.476 Longitude W1041426.916

### NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 15 barrels of water	Volume Recovered: 0 barrels
Source of Release: flow line	Date and Hour of Occurrence: 2/5/2015	Date and Hour of Discovery: 2/5/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A Non-Apache third party contractor installing a 3 in water line ran over padded poly flow line and ruptured the line with rippers on blade. The line was isolated and repaired.

Describe Area Affected and Cleanup Action Taken.\*

The entire release was in pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bruce Baker</u>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Environmental Technician		Approval Date: <u>2/19/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	
Date: 2/19/2015		Remediation per O.C.D. Rules & Guidelines	
Phone: (432) 631-6982		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

MIT REMEDIATION PROPOSAL NO  
LATER THAN: 3/19/15

2RP-2827