

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 19 2015

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1505131025 OPERATOR Initial Report Final Report

Name of Company: Apache Corporation <u>873</u>	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name EAU Emulsion Line (nearest well D State 88)	Facility Type: Oil Well
Surface Owner State	Mineral Owner
API No. 30-15-40233	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	34	17S	28E	1460'	FSL	1755'	FEL	Eddy

Latitude N32.788212 Longitude W104.161188

NATURE OF RELEASE

Type of Release: oil and produced water	Volume of Release 10 barrels of water and 5 barrels of oil	Volume Recovered 7 barrels of water and 3 barrels of oil
Source of Release: fiberglass line	Date and Hour of Occurrence 2/7/2015	Date and Hour of Discovery 2/7/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The 45 on six inch fiberglass line failed. The line was isolated and repaired. Vacuum truck was dispatched to pick-up standing fluid.

Describe Area Affected and Cleanup Action Taken.*
Approximately 11,000 square feet of pasture land and bar ditch along CR 360. The area was dusted with caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bruce Baker</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Environmental Technician	Approval Date: <u>2/20/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>larry.baker@apachecorp.com</u>	Conditions of Approval:	
Date: <u>2/19/2015</u> Phone: <u>(432) 631-6982</u>	Remediation per O.C.D. Rules & Guidelines	
SUBMIT REMEDIATION PROPOSAL NO		
ATER THAN: <u>3/20/15</u>		

Attached

* Attach Additional Sheets If Necessary

2RP-2828