Ford 3160-5 (March 2012)

(Instructions on page 2)

NMOCD

UNITED STATES DEPARTMENT OF THE INTERIOR

NATOBLISONSERVATION ARTESIA DISTRICT

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

BUREAU OF LAND MANAGEMENT

FEB 11 2015

APPROVED FOR 3 MONTH PERIOD

MAY 0 6 2015

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Hours Prior To The Scheduled Casing Integrity Test. For Wells In Chaves And Roosevelt County, During

Or After Office Hours Call (575) 626-5749.

Office Hours Or After Office Hours Call (575) 627-0205. Engineer On Call During Office Hours Call (575) 627-0275 5. Lease Serial No. 6. If Indian, Allottee or Tribe Name

abandoned wen. Os	SE FOITH 3 100-3 (AFD) TOT.				
SUBMIT II	N TRIPLICATE Other instruction	7. If Unit of CA/Agr	eement, Name and/or No.		
1. Type of Well Oil Well Gas Well Other TNICCTION			8. Well Name and N	Ey Lake Queen #0011	
2. Name of Operator Tandem Energy Corporation	,	9. API Well No.	.1		
3a. Address 3b. Phone No. finelude are			30-005-60244 10. Field and Pool or Exploratory Area		
2700 Post Oak Blvd., Ste. 1000, Houston,TX 77056	7326	Luck	Lucker Lake		
4. Location of Well (Footage, Sec., T.,R.,		11. County or Parish	11. County or Parish, State		
1980 FNL 660FEL 21 155 29E			<u> </u>	Chaves	
12. CHECK	THE APPROPRIATE BOX(ES) TO	INDICATE NATURE C	OF NOTICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION TYPE OF ACT			OF ACTION	·	
Notice of Intent	Acidize	Decijen 🔄	Production (Start/Résume) Water Shut-Off		
Notice of Intent	After Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Showedness Kelasti	Change Plans	Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
4. GIH WPKR + 5. Set PKR + PSI 6. ROMO pulling 7. Schedule wit 8. Rtn well to in	pandonment Notices must be filed onlinal inspection.) POOH withog. eving re-dressed. GI psi test the the test backside to e gunit. rnessed psi test. yection. SEE ATT CONDIT	ly after all requirements, H to ensure	including reclamation. have be . No fill. Clean g leak.	en completed and the operator has	
14. Thereby certify that the foregoing is true	and correct. Name (Printed/Typed)				
L. Kiki Lockett	Title Regulatory	Title Regulatory Specialist			
Signature Local	Date 01/20/201	Date 01/20/2015			
	THIS SPACE FOR FE	EDERAL OR STA	TE OFFICE USE		
Approved by					
ORIG: SGD.) D	PETRO	LEUM ENGINEER	Date FEB 0 6 2015		
Conditions of approval, if any, are attached that the applicant holds legal or equitable title entitle the applicant to conduct operations the	e to those rights in the subject lease whi	nt or certify.		Duc	
Title 18 U.S.C. Section 10			willfully to make to any departm	nent or agency of the United States any false,	
fictitious or fraudulent stat Please Cor	ntact The BLM Roswell Field O	Office At Least 24		*	

Mechanical Integrity Test Conditions of Approval

Tandem Energy Corporation South Lucky Lake Queen Unit Well No. 1F, API 30-005-60244 1980FNL & 660FEL Sec. 21, T15S-R29E

- 1. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00 AM through 3:00 AM for the period of March 1 through June 15.
- 2. Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established.
- 3. The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 4. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 5. Make arrangements 24 hours before the test for BLM to witness. In Chaves and Roosevelt Counties E-Mail Robert Hoskinson (rhoskins@blm.gov) or phone 575-627-0205.
- 6. Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 7. Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry.
- 8. Submit the original subsequent sundry with three copies to BLM Roswell Field Office.
- Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
 - a) Approved injection pressure compliance is required.
 - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
 - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 10. Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 11. The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 12. A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 13. Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Roswell Field Office, Petroleum Engineering within 5 days.

- 14. Gain of annular fluid pressure requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0 psia. Notify the BLM's authorized officer ("Robert Hoskinson" <<u>rhoskins@blm.gov></u>, cell phone 575-627-0205).
- 15. Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry.