

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

FEB 25 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1505734713

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229/137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Tex Mack #202	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-35914
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 2	Township 17S	Range 31E	Feet from the 990'	North/South Line South	Feet from the 1650'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.8590803868665 Longitude -103.843618143308

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 25 bbls Oil	Volume Recovered: 20 bbls Oil
Source of Release: Heater Treater	Date and Hour of Occurrence: 2/7/2015 9:00 am	Date and Hour of Discovery: 2/7/2015 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

1/4" nipple on oil leg corroded and caused leak. Vacuum trucks were dispatched to recover all standing fluid and micro blaze was applied to the pasture.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the facility but an over spray in pasture occurred. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 2/26/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: February 25, 2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

ATER THAN: 3/26/15

2RP-2840