

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit Battery #158	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31690
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
A	7	24S	30E	660	North	660	East	Eddy

Latitude N 32.237400 Longitude W 103.914150

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 230 bbls	Volume Recovered: 200 bbls
Source of Release: Water transfer pump seal and piping failure.	Date and Hour of Occurrence: 3/21/11 Time unknown	Date and Hour of Discovery: 3/21/11 Time 7:40 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Tony Savoie	Date and Hour: 3/21/11 at 8:20 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A water transfer pump seal and bearings failed causing excessive vibration on the discharge piping of the pump. The power was shut off and valves were closed isolating the pump. The pump was replaced later the same day.



Describe Area Affected and Cleanup Action Taken.*

The entire area of the earthen containment was covered with produced water, approximately 4500 sq.ft. The free standing water was removed and the saturated area around the tanks and inside the containment was excavated and stockpiled on-site. Remediation activities were under way under an approved remediation plan. The caliche pad area measuring approximately 2000 sq.ft. was affected by the misting of the produced water being sprayed into the air.

Reference 2RP-717

The release was remediated as per NMOCD approval. Please reference the attached Remediation Summary & Site Closure Request for remediation details. Date June 2012

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 3/2/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 1/3/14 <u>3/3/15</u> Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

2RP-717