


2RP-946



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

### Release Notification and Corrective Action

**OPERATOR**  Initial Report  Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: H.E. West B 66	Facility Type: Water Flood

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001527785
--------------------	--------------------	---------------------

### LOCATION OF RELEASE

Unit Letter B	Section 10	Township 17S	Range 31E	Feet from the 1230	North/South Line N	Feet from the 1435	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32°51' 10.8 Longitude: -103°51' 13.3

### NATURE OF RELEASE

Type of Release: Land	Volume of Release: 1 / 1	Volume Recovered: 0 / 0
Source of Release: Oil / Produced Water	Date and Hour of Occurrence: 10/26/2011 - 1030	Date and Hour of Discovery: 10/26/2011 - 1100
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Joe Hernandez	Date and Hour: 10/27/2011 - 1330	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Wellhead stuffing box leaked due to flowline back pressure valve pressured up well control set on hand move to D-jax control.

Describe Area Affected and Cleanup Action Taken.\* : Affected area was around the well head. The area was excavated and replaced with clean caliche. The excavated material was hauled to Lea Land for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Jose Hernandez	Approved by District Supervisor:	
Title: Foreman	Approval Date: 2/13/15	Expiration Date: N/A
E-mail Address: jhernandez@linneenergy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 1/30/2013 Phone: 575-738-1739		

\* Attach Additional Sheets If Necessary

2RP-946