

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

APR 16 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1511048472

OPERATOR

Initial Report Final Report

Name of Company <i>Cimarex Energy</i> <i>1102683</i>	Contact <i>Christine Alderman</i>
Address <i>600 N Marienfeld Ste 600 Midland TX</i>	Telephone No. <i>432-853-7059</i>
Facility Name <i>Wigeon 23 Fed Com 2</i>	Facility Type <i>Production</i>

Surface Owner	Mineral Owner	API No. <i>30-015-33684</i>
---------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>H</i>	<i>23</i>	<i>25S</i>	<i>26E</i>	<i>1350</i>	<i>N</i>	<i>1300</i>	<i>E</i>	<i>Eddy</i>

Latitude *32.1189* Longitude *-104.2591*

NATURE OF RELEASE

Type of Release <i>produced water</i>	Volume of Release <i>15 bbls</i>	Volume Recovered <i>1 bbl</i>
Source of Release <i>flowline</i>	Date and Hour of Occurrence <i>04/07/2015</i>	Date and Hour of Discovery <i>04/07/2015</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher/Sol Hughes</i>	
By Whom? <i>Christine Alderman</i>	Date and Hour <i>4/8/2015 9:53 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 4" poly line at the edge of location is connected to an 8" trunk line. The valve somehow got opened and check valve failed. There was evidence of the line being run over by a truck which may have damaged the check valve.

Describe Area Affected and Cleanup Action Taken.*
Affected an area on the back side of the battery on location. I will have consultant asses, delineate and prepare work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <i>Christine Alderman</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>ESH Supervisor</i>	Approval Date: <i>4/17/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>calderman@cimarex.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <i>4/17/2015</i> Phone: <i>432-853-7059</i>	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *5/17/15*

2RP-2943