

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

OCT 03 2013

NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Apache Corp.	Contact	Bruce Baker
Address	PO BOX 1849, Eunice, NM 88231	Telephone No.	(432) 631-6982
Facility Name	Roadrunner Federal #1	Facility Type	Production Well
Surface Owner	BLM	Mineral Owner	State
		API No.	30-015-36440

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	17S	31E	1650	FSL	1650	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil/Water	Volume of Release	22 bbls	Volume Recovered	5 bbls
Source of Release	1/4" valve	Date and Hour of Occurrence	6/9/2012	Date and Hour of Discovery	6/9/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Natalie Gladden	Date and Hour	6/15/2012 1:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

1/4" valve on pumping tee was opened by cattle rubbing against it. Valve handle has been removed. Vacuum trucks were called in to recover standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The leak affected a total area of 3,602 square feet including the well pad and 582 square feet of pasture land. Samples were collected and sent to a commercial lab for chloride and TPH analyses. The well pad leak area was excavated to 1.5 ft. and the pasture leak area was excavated to 1 ft. Impacted soils were removed to a NMOCD approved disposal facility. The well pad leak area was backfilled with clean imported caliche and leveled. The pasture excavation was backfilled with clean imported soil and contoured to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by District Supervisor: <i>H. Baker</i>	
Title: Environmental Tech		Approval Date: <i>4/20/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval: <i>Final</i>	
Date: <i>8-30-13</i> Phone: (432) 631-6982		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1195