

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company – Devon Energy	Contact – Roy White, Foreman
Address – 6488 Seven Rivers Hwy – PO Box 250	Telephone No. – 575-513-1741
Facility Name – Parkway # 21	Facility Type

Surface Owner	Mineral Owner	Lease No. API # 30-015-32686 2RP-706
---------------	---------------	--------------------------------------


LOCATION OF RELEASE

Unit Letter P	Section 28	Township 19S	Range 29E	Feet from the 330'	North/South Line South	Feet from the 400'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.62534 Longitude -104.07259

NATURE OF RELEASE

Type of Release – Oil	Volume of Release 152 bbls	Volume Recovered 23 bbls
Source of Release – Load line valve in front of tank broke	Date and Hour of Occurrence 1/23/11 – 10:30 am	Date and Hour of Discovery 1/23/11 – 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Darold Gray – OCD	
By Whom? – Roy White, Foreman	Date and Hour 1/23/11 – 11:55 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Load line valve in front of tank froze and broke in two. Tanks were cleaned, bottoms recoated and all valves replaced. A vacuum truck was used to recover 23 bbls of oil. Removed impacted soil from release area.

Describe Area Affected and Cleanup Action Taken.*

Impacted area 10'x100' in front of tanks. Impacted area was excavated to the depth of 1 foot; contaminated soil transported to a NMOCD approved facility for disposal. The area was backfilled to grade using new material transported from local borrow pit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: David Adkins, TALON/LPE	Approved by District Supervisor:	
Title: Agent/Devon Energy	Approval Date: 4/22/15	Expiration Date:
E-mail Address: dadkins@talonlpe.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/23/11	Phone: 575-746-8768	

* Attach Additional Sheets If Necessary

2RP 706
Final