

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company : Devon Energy	Contact : Roger Hernandez	
Address : PO Box 250, Artesia, NM 88211	Telephone No. : 575-748-5238	
Facility Name : Littlefield AB #5	Facility Type: Oil well	
Surface Owner	Mineral Owner:	Lease No. : API #30-015-20001 2RP-988

LOCATION OF RELEASE

Unit Letter M	Section 22	Township 18S	Range 31E	Feet from the 660'	North/South Line FSL	Feet from the 660'	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------

Latitude 32.72668 Longitude -103.86361

NATURE OF RELEASE

Type of Release : OIL & Produced Water	Volume of Release : 3 bbls oil & 7 bbls PW	Volume Recovered: 3 bbls oil
Source of Release : Flow line union	Date and Hour of Occurrence: 12/9/11 10:18 am	Date and Hour of Discovery: 12/9/11 10:18 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD/ Jeff Lakin BLM / Trish Badbear	
By Whom?	Date and Hour : NMOCD 12/9/11 12:35 pm; BLM 12/9/11 12:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A union loosened due to the recent freeze, while thawing it caused a leak. A vacuum truck was immediately called and the union was tightened.		
Describe Area Affected and Cleanup Action Taken.* Talon/LPE was also contacted for the correction of the release. The impacted area was excavated to a depth of 2.5 foot deep, analytical testing was completed and the impacted soil was transported to Lea Land, LLC an approved disposal facility. The excavated area was backfilled to grade with new material transported from a local borrow pit.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Roger Hernandez 	OIL CONSERVATION DIVISION	
Printed Name: Roger Hernandez	Approved by District Supervisor: 	
Title: Assistant Production Supervisor	Approval Date: 4/22/15	Expiration Date:
E-mail Address: roger.hernandez@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/25/2012 Phone: 575-748-5238		

* Attach Additional Sheets If Necessary

Final - 988