

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NM OIL CONSERVATION  
ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAY 07 2015  
Submitted to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**nAB1513137846**

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <b>229137</b>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Unit #46H	Facility Type: Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-41866
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter: D	Section: 5	Township: 26S	Range: 28E	Feet from the: 190'	North/South Line: North	Feet from the: 550'	East/West Line: West	County: Eddy
----------------	------------	---------------	------------	---------------------	-------------------------	---------------------	----------------------	--------------

Latitude 32.0784096731862 Longitude -104.116248710771

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 100 bbls	Volume Recovered: 70 bbls
Source of Release: Poly Flowline	Date and Hour of Occurrence: 4/16/2015 12:00 am	Date and Hour of Discovery: 4/16/2015 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 4/17/2015 2:19 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused when a flowline was damaged after heavy equipment ran over the line. Vacuum trucks were dispatched to recover all standing fluid and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area was the pasture to the north of the lease road. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 5/11/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 7, 2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 6/12/15

2RP-2994