

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 4 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

*NAB 1515049001*

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Devon Energy Production 60137</i>	Contact <i>Mike McMahan</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88220</i>	Telephone No. <i>575.706.41.65</i>
Facility Name <i>Burton Flat Deep Unit 52</i>	Facility Type <i>Oil</i>

Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i>	API No. <i>30-015-40693</i>
------------------------------	------------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	3	21S	27E	4000	FNL	50	FEL	EDDY

Latitude: 32.51155 Longitude: 104.1685

**NATURE OF RELEASE**

Type of Release Spill <i>Produced Water</i>	Volume of Release <i>2 BBL</i>	Volume Recovered <i>0 BBL</i>
Source of Release <i>Pin Hole leak in transfer line</i>	Date and Hour of Occurrence <i>6/1/15 at 1:30 PM</i>	Date and Hour of Discovery <i>6/1/15 at 1:30 PM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Jim Amos - BLM</i>	
By Whom? <i>Gilbert Sanchez</i>	Date and Hour <i>6/2/15 8:00 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

June 01, 2015 on the Burton Flat Deep Unit 52/56 at 1:30 pm A Devon lease operator found a pin hole leak on the water transfer line. A 5" clamp was placed over the pin hole to stop the leak.

Describe Area Affected and Cleanup Action Taken.\*

Tex-Mex vacuum truck was called out to empty line for repairs and clean up. A 2 BBL spill of produced water and 0 recovered on side of lease road on pasture. Environmental company will be called to evaluate area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jeanette Barron</b>	Signed By: <i>Mike McMahan</i>	
Title: <b>Field Admin Support</b>	Approved by Environmental Specialist:	Approval Date: <i>6/5/15</i> Expiration Date: <i>N/A</i>
E-mail Address: <b>Jeanette.barron@dvn.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6/4/15</i> Phone: <i>575.748.1813</i>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/9/15**

*2RP-3031*

\* Attach Additional Sheets If Necessary