

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 26 2015

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1518142271 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-29 SWD Tank Battery	Facility Type: SWD

Surface Owner: State of N.M.	Mineral Owner: State of N.M.	API No. 30-015-27735
------------------------------	------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
K	36	22S	30E	1980	South	2310	West	Eddy

Latitude N 32.346432 Longitude W 103.835934

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 110 bbls.	Volume Recovered: 40 bbls.
Source of Release: 4" SWD pump discharge line	Date and Hour of Occurrence: 6/22/15 Time unknown	Date and Hour of Discovery: 6/22/15 at about 5:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 6/22/15 at 6:36 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" pipe fitting failed on the discharge of the SWD transfer pump. The pump was shut down and the fitting was replaced.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 5,000 sq.ft. of pasture area. All of the free standing fluid was recovered with a vacuum truck. Twenty bbls of PW was recovered from the 0 Perm containment and 20bbls off the ground. A portion of the impacted area has a liner installed at about 3 ft. in depth. This liner was installed during a previous closed remediation at the location.

The spill area will be cleaned up in accordance to the NMOCD remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By: <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: 6/30/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/26/15	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: **8/1/15**

2RP-3082