

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 08 2015

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA B1519554769

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: COINFLIP STATE COM #002H	Facility Type:

Surface Owner: STATE	Mineral Owner:	API No. 30-015-41937
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 18	Township 20S	Range 30E	Feet from the 580	North/South Line North	Feet from the 570	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.5790367 Longitude -104.0180969

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls Oil ; 15 bbls Water	Volume Recovered: 2 bbls Oil; 14 bbls PW
Source of Release: Dump Valve	Date and Hour of Occurrence: 6/20/2015 3:40 am	Date and Hour of Discovery: 6/20/2015 3:40 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when the housing ruptured on a dump valve on a FWKO. Vacuum trucks were dispatched to recover all standing fluids.

Describe Area Affected and Cleanup Action Taken.*
This release remained within the lined facility. The facility was cleaned, repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Brennan</i>	
Title: Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address: atrujillo@concho.com	Approval Date: <i>7/14/15</i>	Expiration Date: <i>N/A</i>
Date: July 8, 2015 Phone: 575-748-6940	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3102