

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nab151975043 OPERATOR Initial Report Final Report

Name of Company Oxy Permian Ltd. <i>1610910</i>	Contact CJ Summers
Address 6 Desta Drive, Midland, TX 79705	Telephone No. (432) 685-5824
Facility Name Harroun 15-3 SWD Facility	Facility Type SWD
Surface Owner Fee	Mineral Owner
API No. 30-015-29233	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	15	24S	29E					Eddy County, NM

Latitude N 32.21988° Longitude W 103.96499°

NATURE OF RELEASE

Type of Release Oil and Produced water	Volume of Release 5 bbls oil, 15 bbls produced water	Volume Recovered 0 bbls
Source of Release Truck driver ran over skim tank and ho high alarm	Date and Hour of Occurrence 06/08/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson-NMOCD	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 06/10/2015 @ 8:39 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 14 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A truck driver ran over a skim tank and caused 5 bbls of oil and 15 bbls of produced water to leak onto the ground. No fluids were recovered and precautionary measures have been taken to prevent future mishaps.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 45' x 45' with all of the leak staying inside the lined battery on location. Remediation will be completed according to a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: CJ Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: 7/16/15	Expiration Date: N/A
E-mail Address: chancey_summers@oxy.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 7-13-15 Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/20/15 **2RP-3118**

* Attach Additional Sheets If Necessary