

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 14 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED
also file with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1519828986

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>116696</i>	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Two Marks 36 State #4 SWD Battery	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-15-34833

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	21S	24E					Eddy County, NM

Latitude N 32.42960° Longitude W 104.45840°

NATURE OF RELEASE


Type of Release	Oil and produced water	Volume of Release	0.5 bbl oil, 14.5 bbls produced water	Volume Recovered	0 bbls
Source of Release	Leak in a 2.875" steel oil dump line	Date and Hour of Occurrence	06/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/25/2015 @ 11:17 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A leak in a 2.875" steel dump line spilled 0.5 bbl oil and 14.5 bbls of produced water onto the ground. The line was repaired or replaced and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 60' x 60' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: <u>7/17/15</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>Chancey_Summers@oxy.com</u>	Conditions of Approval: <input type="checkbox"/> Remediation per O.C.D. Rules & Guidelines	
Date: <u>7-13-15</u> Phone: (432) 685-5824	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 8/20/15

2RP-3122