

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520255917

OPERATOR

Initial Report Final Report

Name of Company: Mewbourne Oil Company <u>147744</u>	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Tamano 10 Fed Com #7H	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-39685
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 18S	Range 31E	Feet from the 2125'	North/South Line North	Feet from the 455'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7624944 Longitude -103.8622333

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls	Volume Recovered: 8 bbls Oil/ 12bbls PW
Source of Release: Flowline	Date and Hour of Occurrence 7-17-15	Date and Hour of Discovery 7-17-15 10:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 20 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Flow line developed a pin hole causing release. Well was shut in to stop the release.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
Affected area- Leak point was an estimated 250 yards Southeast of well head in pasture down pipeline right of way. 2000 square feet of the right of way was affected. Vacuum truck was used to recover all standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Z. Thomas</u>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Environmental Rep.	Approval Date: <u>7/21/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-20-15 Phone: 575-602-2188	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 8/22/15

2RP-3142

* Attach Additional Sheets If Necessary